

# Rules and Regulations

Federal Register

Vol. 86, No. 142

Wednesday, July 28, 2021

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

## DEPARTMENT OF AGRICULTURE

### Food Safety and Inspection Service

#### 9 CFR Part 352

[Docket No. FSIS-2019-0028]

RIN 0583-AD80

#### Inspection of Yak and Other Bovidae, Cervidae, and Camelidae Species; Correction

**AGENCY:** Food Safety and Inspection Service, U.S. Department of Agriculture (USDA).

**ACTION:** Final rule; correction.

**SUMMARY:** This document corrects the Regulation Identifier Number that appeared in a final rule published in the **Federal Register** on July 15, 2021, regarding the inspection of yak and other bovidae, cervidae, and camelidae species.

**DATES:** This final rule correction is effective July 28, 2021.

**FOR FURTHER INFORMATION CONTACT:** Rachel Edelstein, Assistant Administrator, Office of Policy and Program Development by telephone at (202) 205-0495.

#### SUPPLEMENTARY INFORMATION:

##### Correction

In final rule FR Doc. 2021-15062, beginning on page 37216 in the issue of July 15, 2021, make the following correction: On page 37216, in the second column, the Regulation Identifier Number is corrected to read "RIN 0583-AD80".

Done at Washington, DC.

**Paul Kiecker,**  
Administrator.

[FR Doc. 2021-16059 Filed 7-27-21; 8:45 am]

BILLING CODE 3410-DM-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2020-0442; Project Identifier AD-2020-00260-E; Amendment 39-21640; AD 2021-14-13]

RIN 2120-AA64

#### Airworthiness Directives; Pratt & Whitney Turbofan Engines

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for all Pratt & Whitney (PW) PW2037, PW2037M, PW2040, and F117-PW-100 model turbofan engines. This AD was prompted by a report of an uncontained engine failure resulting from cracks in the knife edge of the high-pressure turbine (HPT) 2nd-stage air seal assembly. This AD requires fluorescent penetrant inspections (FPIs) and visual inspections of the HPT 2nd-stage air seal assembly and, depending on the results of the inspections, replacement of the HPT 2nd-stage air seal assembly with a part eligible for installation. This AD also requires replacement of the affected HPT 2nd-stage air seal assembly, depending on the engine model, at either the next engine shop visit or the next piece-part opportunity. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective September 1, 2021.

**ADDRESSES:** For service information identified in this final rule, contact Pratt & Whitney, 400 Main Street, East Hartford, CT 06118; phone: (800) 565-0140; fax: (860) 565-5442; email: [help24@pw.utc.com](mailto:help24@pw.utc.com); website: <https://fleetcare.pw.utc.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (781) 238-7759. It is also available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0442.

### Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0442; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

#### FOR FURTHER INFORMATION CONTACT:

Carol Nguyen, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7655; fax: (781) 238-7199; email: [carol.nguyen@faa.gov](mailto:carol.nguyen@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all PW PW2037, PW2037M, PW2040, and F117-PW-100 model turbofan engines. The NPRM published in the **Federal Register** on June 1, 2020 (85 FR 33043). The NPRM was prompted by a report of an uncontained engine failure resulting from cracks in the knife edge of the HPT 2nd-stage air seal assembly. After further analysis, it was determined that the knife-edge crack was due to seal rubbing that elevated the HPT 2nd-stage air seal assembly temperature and induced fatigue. In the NPRM, the FAA proposed to require initial and repetitive borescope inspections (BSIs), FPIs, and visual inspections of the HPT 2nd-stage air seal assembly and, depending on the results of the inspections, replacement of the HPT 2nd-stage air seal assembly with a part eligible for installation. The NPRM also proposed to require replacement of the affected HPT 2nd-stage air seal assembly, depending on the engine model, at either the next engine shop visit or the next piece-part opportunity. The FAA is issuing this AD to address the unsafe condition on these products.