

SAMPLE LETTER
MODIFICATIONS TO BREAKING OPERATION AT EGG PRODUCTS PROCESSING
FACILITY

December 19, 2013

Mr. Edward Eggmanship
Plant Manager
New Way Farm
2222 U.S. Highway Route 66
Anytown, USA & Zip code

Dear Mr. Eggmanship:

We have reviewed drawings and supplemental information submitted to the District Office reflecting modifications to breaking operation at your egg products processing plant near Anytown, USA.

The drawings show the replacement of your current egg breaking system with a Sanovo egg breaking and separating system. The Sanovo Opti-breaker model 18 is the type of breaking system that does not present the shell with the contents of the broken egg for organoleptic inspection by the machine operator. The quality of eggs presented for breaking on a system of this type is limited and must be carefully monitored by the processor. The program currently used for the Diamond-MOBA egg breaking system would be acceptable.

The installation appears to be in compliance with the Regulations Governing the Inspection of Eggs and Egg Products according to 9 CFR 590. Therefore we are declaring no-objection related to these drawings applicable to official plant #0045 G.

Floor Plan – Facility Layout – Breaking Room

The acceptance of these drawings is conditional, pending a final survey by Field Operations to determine that all facilities, equipment and installations are in accordance with the regulations. Upon completion of the final survey a member of Field Operations will advise you of conformance with the regulations.

Sincerely,

District Manager